



August 2008

MV Dorothea: corrosion at superstructure, insufficient insulation of hot surfaces in engine room, etc.